

ELEMENTOS VALORADOS

Operación	Posición	Descripción	Referencia	Descuento	Precio
PINTURA PIEZA NUEVA	1485	PANEL PUERTA DL.I.		0.00 €	0.00 €
SUSTITUIR	1785	PANEL PUERTA TR.I.	9011 99	0.00 €	274.57
PINTURA PIEZA NUEVA	1785	PANEL PUERTA TR.I.		0.00 €	0.00 €
SUSTITUIR	2581	PARAGOLPES TR.	308-08323	0.00 €	518
PINTURA PIEZA NUEVA	2581	PARAGOLPES TR.		0.00 €	0.00 €
SUSTITUIR	2585	FALDON TR.PARAGOLPES	308-08620	0.00 €	302
SUSTITUIR	2587	MOLDURA I.PARAGOL.TR	7452 PZ	0.00 €	86.65
SUSTITUIR	2621	SOP.I.PARAGOLPES TR.	8525 NN	0.00 €	40.97
SUSTITUIR	2653	SENSOR TR.EXT.I.APAR	021016075010	0.00 €	31.7
PINTURA PIEZA NUEVA	2653	SENSOR TR.EXT.I.APAR		0.00 €	0.00 €
SUSTITUIR	2655	SENSOR TR.INT.I.APAR	021016075010	0.00 €	31.7
PINTURA PIEZA NUEVA	2655	SENSOR TR.INT.I.APAR		0.00 €	0.00 €
SUSTITUIR	2711	FALDON TR.CPL.	16 105 800 80	0.00 €	335.17
PINTURA PIEZA NUEVA	2711	FALDON TR.CPL.		0.00 €	0.00 €
SUSTITUIR	3281	PILOTO TR.I.	11-11884-01-2	0.00 €	151.97
SUSTITUIR	3481	ALETA TR.I.CPL.	8525 LT	0.00 €	1474.82
PINTURA PIEZA NUEVA	3481	ALETA TR.I.CPL.		0.00 €	0.00 €
SUSTITUIR	3783	REJILLA AIREAC.TR.I	7243 AZ	0.00 €	33.24
SUSTITUIR	4201	CONCHA PASE RUE.TR.I	8533 CN	0.00 €	72.47
SUSTITUIR	4205	FALDILLA TR.I.	8533 55	0.00 €	44.02
SUSTITUIR	9081	PUENTE TR.	4040629	0.00 €	339.44
SUSTITUIR	9161	EJE ACOPLAMEN.TRA.I	5176 41	0.00 €	138.15
SUSTITUIR	9201	AMORTIGUADOR TR.I.	JAPMM-00635	0.00 €	64.65
SUSTITUIR	1485	PANEL PUERTA DL.I.	9009 H2	0.00 €	344.94

Mano de obra

	UT	PRECIO / H	
Chapa:	242.00	36.00 €	871.20 €
Mecánica:	33.00	36.00 €	118.80 €
Pintura:	0.00	36.00 €	234.00 €
Total:			1,224.00 €

Materiales

Piezas:			4,284.46 €
Otros:			0.00 €
Pintura:			201.57 €
Total:			4,284.46 €

Total Valorado:			5,710.03 €
Descuento:			-285.50 €
Suma total sin IVA:			5,424.53 €
Total con 21 % de IVA:			6,563.68 €
Franquicia:			200.00 €
Suma total:			6,363.68 €